

**LBUSD Early Education Water Quality Testing - Updated January 2024**

Number of water fixtures tested, listed by ranges in parts per billion (PPB) lead. The state standard is 5.5 PPB or less for early education sites.

School Site	Location	<1	1-5 PPB	Notes
Adams CDC	Room 28	1	1	Sample taken from handwashing station, <1.00 PPB
	Room 29	1	1	Sample taken from handwashing station, <1.00 PPB
	Room 6	0	1	Sample taken from handwashing station, 2.33 PPB
	Room 5	0	1	Sample taken from handwashing station, 2.29 PPB
	Room 5 Restroom	1	1	Sample taken from drinking fountain <1.00 PPB
	Playground	4	4	Samples taken from outdoor drinking fountain trough <1.00 PPB each
Bethune Head Start	Office entrance	1	1	Sample taken from handwashing station, <1.00 PPB
	Office kitchen	1	1	Sample taken from handwashing station, <1.00 PPB
	Playground	0	1	Sample taken from outdoor drinking fountain, <1.12 PPB
	Playground	1	1	Sample taken from outdoor drinking fountain, <1.00 PPB
	Room 1	1	1	Sample taken from drinking fountain, <1.00 PPB
	Room 1	1	1	Sample taken from handwashing station, <1.00 PPB
	Room 2	1	1	Sample taken from drinking fountain, <1.00 PPB
	Room 2	1	1	Sample taken from handwashing station, <1.00 PPB
Buffum Head Start	Room K2	0	1	Sample taken from drinking fountain, 1.13 PPB
	Room K2	0	1	Sample taken from handwashing station, 3.82 PPB
	Room K1	1	1	Sample taken from handwashing station, <1.00 PPB
	Room K1	1	1	Sample taken from handwashing station, <1.00 PPB
Burroughs Head Start	Bungalow B1	0	2	Samples taken from drinking fountain, 1.02 PPB, and handwashing station, 4.65 PPB (drinking fountain results after repairs)
	Bungalow B2	1	1	Sample taken from handwashing station, 1.13 PPB (<1 result after repairs)
	Playground	3	0	Samples taken from (3) drinking fountain bubblers, <1.00 PPB, <1.00 PPB, <1.00 PPB
Burbank CDC	Kitchen	0	1	Sample taken from kitchen sink, 2.28 PPB
	Playground	1	3	Samples taken from outdoor drinking fountains, 1.88 PPB, 2.66 PPB and 3.12 PPB
Carmelitos Head Start	Room 1	0	4	Samples taken from one drinking fountain (1.66 PPB) and three handwashing stations (1.87 PPB, 2.12 PPB & 2.62 PPB)
	Room 2	2	1	Sample taken from handwashing station, 5 PPB (<1 results after repairs)
	Playground	3	0	Samples taken from one drinking fountain <1.00 PPB and one handwashing station <1.00 PPB
Carver YMCA	Cafeteria	2	1	Sample taken from kitchen sink, 4.13
Central Facilities Center CDC	Kitchen	0	1	Sample taken from handwashing station, 1.95 PPB
	Lounge	1	0	Sample taken from handwashing station, <1.00 PPB
	Room 305	0	2	Samples taken from drinking fountain, 2.13 PPB (results after repairs), and handwashing station, 2.70 PPB
	Room 303	1	2	Samples taken from drinking fountain, 4.88 PPB, and handwashing station, 1.49 PPB (handwashing station results after repairs)
	Room 302	1	2	Samples taken from drinking fountain, 4.62 PPB (results after repairs) and handwashing station, 2.01 PPB (results after repairs)
	Room 301 (indoor)	0	2	Samples taken from drinking fountain, 4.37 PPB, and handwashing station, 1.25 PPB
	Room 301 (indoor)	1	0	Sample taken from drinking fountain, <1.00 PPB
Chavez Head Start	Room 10	0	1	Sample taken from handwashing station, 2.25 PPB
	Room 8	1	0	Sample taken from drinking fountain, <1.00 PPB
	Room 4	1	0	Sample taken from drinking fountain, <1.00 PPB
	Playground	7	1	Samples taken from eight drinking fountains, on at 2.77 PPB and the rest at <1.00 PPB
Carver CDC	Room B28	1	0	Sample taken from handwashing station, <1.00 PPB
	Playground	0	4	Samples taken from outdoor drinking fountains, 2.23 PPB, 2.95 PPB, 3.69 PPB & 4.26 PPB
Dooley CDC	Room 227	0	1	Sample taken from indoor drinking foundation, 1.07 PPB
	Room 227	1	0	Sample taken from handwashing station, <1.00 PPB
	Room 229	2	0	Sample taken from handwashing station, <1.00 PPB
Dooley YMCA	Room 231	2	1	Sample taken from drinking fountain, 2.89 PPB
Edison CDC	Room 53/54 (outdoor)	3	0	Samples taken from three drinking fountain, <1.00 PPB, <1.00 PPB, <1.00 PPB
	Room 54	2	0	Sample taken from indoor handwashing station, <1.00 PPB, <1.00 PPB
	Room 51/52 (outdoor)	1	2	Samples taken from drinking fountains, 1.21 PPB and 1.78 PPB
	Room 51	1	1	Sample taken from handwashing station, 1.16 PPB
Edison Head Start	Room 16	0	1	Sample taken from handwashing station, 4.01 PPB
	Room 18	0	1	Sample taken from handwashing station, 2.91 PPB
	Room 19	0	3	Samples taken from drinking fountains, 2.81 PPB and 3.83 PPB, and handwashing station, 3.03 PPB

School Site	Location	<1	1-5 PPB	Notes
Elm Head Start	Bungalow 3	3	0	Samples taken from handwashing station, <1.00PPB, <1.00PPB and drinking fountain, <1.00 PPB
	Bungalow 4	1	1	Sample taken from drinking fountain, <1.00 PPB and handwashing station, 5.14 PPB
	Bungalow 2	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 1A	3	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB, <1.00 PPB
	Room 1B	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Playground	3	0	Sample taken from three drinking fountains, <1.00 PPB, <1.00 PPB, <1.00 PPB
Emerson CDC	Room 5	2	0	Samples taken from handwashing station, <1.00 PPB, <1.00 PPB
Gant CDC	Room 5	1	1	Sample taken from handwashing station, 4.52 PPB
	Playground	2	1	Sample taken from outdoor drinking fountain, 1.39 PPB
Gant YMCA	Cafeteria	0	1	Sample taken from drinking fountain, 2.82PPB
	Playground	4	0	Samples taken from drinking fountains, <1.00 PPB, <1.00 PPB, <1.00 PPB, <1.00 PPB
Garfield CDC	Room 25103	1	0	Sample taken from handwashing station, <1.00 PPB
	Room 25102	1	0	Sample taken from handwashing station, <1.00 PPB
	Room 25101	2	0	Sample taken from handwashing station, <1.00 PPB
Garfield Head Start	Room 2104	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 3102	3	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Playground	2	1	Samples taken from outdoor drinking fountains, 1.70 PPB, <1.00 PPB, <1.00 PPB
Gompers YMCA	Cafeteria	0	2	Samples taken from drinking fountains, 1.24 PPB and 1.95 PPB
	Playground	0	3	Samples taken from outdoor drinking fountains, 1.39 PPB, 1.56 PPB and 3.90 PPB
Grant CDC	Room 11	2	0	Samples taken from outdoor drinking fountains, <1.00 PPB, <1.00 PPB
	Room 30	1	1	Sample taken from indoor drinking foundation, 1.27 PPB
	Playground	3	0	Samples taken from outdoor drinking fountains, <1.00PPB, <1.00 PPB and <1.00 PPB
Harte Head Start	Staff Restroom	1	0	Sample taken from handwashing station, <1.00 PPB
	Playground	3	0	Samples taken from drinking foundation, <1.00 PPB, <1.00 PPB, <1.00 PPB
Herrera YMCA	Room 43	0	2	Samples taken from drinking fountain, 4.94 PPB, and handwashing station, 4.50 PPB
	Playground	0	1	Sample taken from drinking fountain, 2.19 PPB
	Playground	0	0	Sample taken from drinking fountain, 2.28 PPB
	Playground	0	0	Sample taken from bottle filling station, 1.54 PPB
Holmes CDC	Room B25	0	1	Sample taken from handwashing station, 1.72 PPB
	Playground	0	1	Sample taken from outdoor drinking fountain, 2.98 PPB
Hudson CDC	Room 2	2	2	Samples taken from drinking fountain, 2.74 PPB, and handwashing station, 4.31 PPB (handwashing results after repairs)
Hudson Head Start	Bungalow 37	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Bungalow 36	2	0	Sample taken from handwashing station, <1.00 PPB, <1.00 PPB
Jordan Plus Head Start	Room 1	1	2	Samples taken from drinking fountain, 2.02 PPB, and handwashing station, 1.92 PPB
	Room 2	0	4	Sample taken from drinking fountains, 1.30 PPB and 4.24 PPB (results after repairs),and handwashing stations, 1.37 PPB and 3.86 PPB
	Playground	2	1	Samples taken from drinking fountains, 1.68 PPB
Kettering YMCA	Bungalow 21		2	Samples taken from drinking fountain, 1.34 PPB, and handwashing station, 3.69 PPB (results after repairs)
	Bungalow 20	1	1	Sample taken from drinking fountain, 3.37 PPB
	Playground	2	3	Samples taken from drinking fountains, 1.28 PPB and 1.49 PPB, and bottle filling station, 2.23 PPB
King CDC	Room 2	0	1	Sample taken from handwashing station, 2.41 PPB (results after repairs)
	Playground	2	1	Sample taken from drinking fountain, 1.10 PPB
King Head Start	Bungalow 1	1	2	Samples taken from drinking fountain, 1.83 PPB, and handwashing station, 2.19 PPB
	Bungalow 2	4	1	Sample taken from drinking fountain, 1.25 PPB
Lafayette CDC	Room 6	3	0	Sample taken from drinking fountain, <1.00 PPB, and handwashing station, <1.00 PPB
Lincoln CDC	Bungalow B2	1	1	Sample taken from drinking fountain, 5 PPB (results after repairs)
	Bungalow B1	1	1	Sample taken from drinking fountain, 3.85 PPB (results after repairs)
Los Cerritos YMCA	Playground	0	1	Sample taken from drinking fountain, 4.57 PPB
	Playground	0	1	Sample taken from drinking fountain, 3.78 PPB
	Playground	0	1	Sample taken from bottle filler, 4.07 PPB
	Playground	1	0	Sample taken from drinking fountain, <1.00 PPB
	Playground	1	0	Sample taken from bottle filler, <1.00 PPB
	Playground	0	1	Sample taken from bottle filler, 1.33 PPB
	Playground	0	1	Sample taken from drinking fountain 3.43 PPB
Playground	0	1	Sample taken from drinking fountain 2.20 PPB	

	Playground	0	1	Sample taken from drinking fountain 2.11 PPB
	Playground	1	0	Results after repairs.
	Playground	0	1	Sample taken from drinking fountain 1.75 PPB
Lowell YMCA	Hallway	2	0	Results after repairs.
	Playground	6	1	Sample taken from bottle filling station, 5 PPB

School Site	Location	<1	1-5 PPB	Notes
MacArthur CDC	Room 1109	2	0	Sample taken from handwashing station, <1.00 PPB, and drinking fountain, <1.00PPB
	Room 1108	2	0	Sample taken from handwashing station, <1.00 PPB, and drinking fountain, <1.00PPB
	Hallway	2	0	Sample taken drinking fountain, <1.00 PPB, <1.00 PPB
	Playground	0	3	Samples taken from outdoor drinking fountains, 2.68 PPB, 3.20 PPB and 4.00 PPB
Madison YMCA	Cafeteria	2	1	Samples taken from drinking fountains, 1.77 PPB, <1.00 PPB, <1.00 PPB
	Hallway	2	0	Samples taken from drinking fountains, <1.00 PPB, <1.00 PPB
	Playground	3	0	Sample taken from outdoor drinking fountains, <1.00 PPB, <1.00 PPB, and bottle filler, <1.00 PPB
Mann CDC	Room 4	1	0	Sample taken from handwashing station, <1.00 PPB
	Kitchen	2	0	Sample taken from handwashing station, <1.00 PPB, <1.00 PPB
	Playground	3	0	Samples taken from outdoor drinking fountains, <1.00 PPB, <1.00 PPB, <1.00 PPB
McKinley CDC	Room 1102	2	3	Samples taken from one drinking fountain, 1.28 PPB, and handwashing stations, 1.35 PPB and 2.15 PPB
	Room 1105	2	0	Samples taken from one drinking fountain, <1.00 PPB, and handwashing station, <1.00 PPB
McKinley Head Start	Room 1101	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 1101 hallway	1	0	Sample taken from drinking fountain, <1.00 PPB
	Room 1109	1	1	Sample taken from drinking fountain, 1.52 PPB and handwashing station, <1.00 PPB
	Room 1103	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 1103 hallway	4	0	Sample taken from bottle filler, <1.00 PPB and at drinking fountains <1.00 PPB, <1.00 PPB, <1.00 PPB
Muir CDC	Room 33	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 35	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
Naples	Playground	1	2	Samples taken from outdoor drinking fountains, 1.08 PPB and 1.26 PPB
Oropeza Head Start	Room K4	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 8	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Playground	3	0	Sample taken from drinking fountains, <1.00 PPB , <1.00 PPB, <1.00 PPB
Plymouth Head Start	Kitchen	0	1	Sample taken from handwashing station, 1.11 PPB
	Playground	2	0	Sample taken from drinking fountains, <1.00 PPB , <1.00 PPB,
Powell CDC	Room 15	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	K4	2	1	Sample taken from drinking fountain, 2.07 PPB and handwashing station <1.00 PPB, <1.00 PPB
Riley CDC	Preschool	1	2	Sample taken from drinking fountain, 1.73 PPB (results after repairs), and handwashing station, 1.30 PPB
	Room 27108	1	2	Sample taken from drinking fountain, 1.29 PPB, and handwashing station, 2.05 PPB
	Room 27110	2		Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 27110 (outdoor)		1	Sample taken from drinking fountain, 1.42 PPB
	CDC (outdoor)	1	1	Sample taken from drinking fountain, 1.42 PPB, <1.00 PPB
Roosevelt Head Start	Room A105	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 107A	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Playground	3	0	Sample taken from drinking fountains, <1.00 PPB <1.00 PPB, <1.00 PPB
Signal Hill Head Start	Bungalow 1	0	1	Sample taken from drinking fountain, 4.15 PPB
	Bungalow 1	0	1	Sample taken from handwashing station, 1.31 PPB
	Bungalow 2	0	1	Sample taken from drinking fountain, 1.61 PPB
	Bungalow 2	0	1	Sample taken from handwashing station, 1.13 PPB
	Bungalow 2	0	1	Sample taken from handwashing station, 1.48 PPB
Stevenson CDC	Kitchen	1	0	Sample taken from handwashing station, <1.00 PPB
	Playground	0	4	Samples taken from outdoor drinking fountains, 2.53 PPB, 3.13 PPB, 3.94 PPB and 4.20 PPB
Tincher CDC	Kitchen	0	0	Water fixture remains out-of-use until additional testing can be conducted to confirm readings are below the state mandated limit.
	Room 28	0	1	Sample taken from handwashing station, 2.33 PPB
	Room 26	0	1	Sample taken from handwashing station, 1.58 PPB
	Hallway	0	0	Water fixture remains out-of-use until additional testing can be conducted to confirm readings are below the state mandated limit.
	Room 31	0	1	Sample taken from handwashing station, 5 PPB
	Room 30	0	1	Sample taken from handwashing station, 2.35 PPB
	Room 27	0	1	Sample taken from handwashing station, 2.44 PPB
	Room 29	0	1	Sample taken from handwashing station, 5.44 PPB
Playground	1	3	Samples taken from drinking fountains, 1.08 PPB, 1.09 PPB and 1.23 PPB	

School Site	Location	<1	1-5 PPB	Notes
Tincher YMCA	Playground	0	3	Sample taken from drinking fountain, 4.35 PPB, 4.42 PPB and 5 PPB
	Playground	0	0	Water fixtures remain out-of-use. Fixture will be replaced with new water fountain and bottle filling station and retested to confirm readings are below the state mandated limit.
Twain CDC	Room 401	0	1	Sample taken from handwashing station, 1.78 PPB (results after repairs)
	Room 402	0	1	Sample taken from handwashing station, 2.44 PPB
	Playground 401/402 (outdoor)	1	1	Sample taken from drinking fountain, 1.23 PPB
	Room 301 (outdoor)	0	3	Samples taken from drinking fountains, 3.08 PPB, 3.17 PPB and 4.02 PPB
	Room 301 (indoor)	1	0	Sample taken from drinking fountain, <1.00 PPB
	Room 302	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Room 2105 (outdoor)	1	2	Sample taken at drinking fountain, 2.36 PPB and 3.34 PPB
Room 2105 (indoor)	0	1	Sample taken at handwashing station, 1.19 PPB	
Webster CDC	Room 2	0	2	Sample taken from drinking fountain, 3.58 PPB, and handwashing station, 1.54 PPB (handwashing station results after repairs)
	Room 1	0	1	Sample taken from drinking fountain, 2.73 PPB
	Playground	2	0	Sample taken from drinking fountains, <1.00 PPB, <1.00 PPB
Webster Head Start	Bungalow B1	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Bungalow B2	1	1	Sample taken from drinking fountain, 1.04 PPB
	Bungalow B3	1	1	Sample taken from drinking fountain, 2.05 PPB (<1 results after repairs)
	Playground	1	1	Sample taken at drinking fountain, 1.78 PPB
Whittier Head Start	Bungalow 81	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Bungalow 80	2	0	Sample taken from drinking fountain, <1.00 PPB and handwashing station, <1.00 PPB
	Bungalow 82	1	0	Sample taken from handwashing station, <1.00 PPB
	Playground	4	0	Sample taken from drinking fountains, <1.00 PPB <1.00 PPB, <1.00 PPB, <1.00 PPB
Willard CDC	Playground	4	0	Sample taken from drinking fountains, <1.00 PPB <1.00 PPB, <1.00 PPB, <1.00 PPB
	Room 1	3	1	Sample taken at handwashing station, 2.85 PPB (results after repairs)